

SECTION .0500 - SAFETY REQUIREMENTS FOR INDUSTRIAL RADIOGRAPHY OPERATIONS

Codifier's Note: 10 NCAC 03G .2600 was transferred to 15A NCAC 11 .0500 effective January 4, 1990.
Recodification pursuant to G.S. 143B-279.3.

10A NCAC 15 .0501 PURPOSE AND SCOPE

(a) The rules in this Section establish radiation safety requirements for persons utilizing sources of radiation for industrial radiography. The requirements of this Section are in addition to and not in substitution for the other requirements of this Chapter.

(b) The rules in this Section apply to all licensees or registrants who use sources of radiation for industrial radiography; provided, however that nothing in this Section shall apply to the use of sources of radiation in the healing arts.

*History Note: Authority G.S. 104E-7;
Eff. February 1, 1980;
Amended Eff. May 1, 1993;
Transferred and Recodified from 15A NCAC 11 .0501 Eff. February 1, 2015;
Pursuant to G.S. 150B-21.3A, rule is necessary without substantive public interest Eff. June 22, 2019.*