

SECTION .2000 – OIL OR GAS SITE EXPLORATION AND PRODUCTION WASTE MANAGEMENT

15A NCAC 05H .2001 PURPOSE AND SCOPE

The permittee shall manage, control, and dispose of all waste associated with exploration and production (E & P) of oil or gas in accordance with the standards set forth in this Section and all applicable laws and regulations.

*History Note: Authority 113-391(a)(5);
Eff. March 17, 2015.*