

10A NCAC 15 .1305 STORAGE PRECAUTIONS

- (a) Each source of radiation, except accelerators, shall be provided with a storage and transport container. The container shall be provided with a lock, or tamper seal for calibration sources, to prevent unauthorized removal of or exposure to the source of radiation.
- (b) Sources of radiation shall be stored in a manner which will minimize the danger from explosion or fire.

History Note: *Authority G.S. 104E-7;*
 Eff. June 1, 1989;
 Transferred and Recodified from 15A NCAC 11 .1305 Eff. February 1, 2015.